EXECUTIVE SUMMARY - ENFORCEMENT MATTER

Page 1 of 2

DOCKET NO.: 2007-2039-AIR-E **TCEQ ID:** RN100238385 **CASE NO.:** 35136

RESPONDENT NAME: Valero Refining-Texas, L.P.

		•				
ORDER TYPE:						
X_1660 AGREED ORDER	FINDINGS AGREED ORDER	FINDINGS ORDER FOLLOWING SOAH HEARING				
FINDINGS DEFAULT ORDER	SHUTDOWN ORDER	IMMINENT AND SUBSTANTIAL ENDANGERMENT ORDER				
AMENDED ORDEREMERGENCY ORDER						
CASE TYPE:						
<u>X</u> AIR	MULTI-MEDIA (check all that apply)	INDUSTRIAL AND HAZARDOUS WASTE				
PUBLIC WATER SUPPLY	PETROLEUM STORAGE TANKS	OCCUPATIONAL CERTIFICATION				
WATER QUALITY	SEWAGE SLUDGE	UNDERGROUND INJECTION CONTROL				
MUNICIPAL SOLID WASTE	RADIOACTIVE WASTE	DRY CLEANER REGISTRATION				
SITE WHERE VIOLATION(S) OCCURR TYPE OF OPERATION: Oil and gas refin	ED: Valero Refining Texas City Refinery, 1301 Lo	op 197 South, Texas City, Galveston County				
SMALL BUSINESS: Yes X	No					
OTHER SIGNIFICANT MATTERS: There are no complaints. There are four additional pending enforcement actions regarding this facility location, Docket Nos. 2007-0603-AIR-E, 2007-1234-AIR-E, 2007-1413-AIR-E, and 2007-1512-AIR-E.						
INTERESTED PARTIES: No one other than the ED and the Respondent has expressed an interest in this matter.						
COMMENTS RECEIVED: The Texas Register comment period expired on May 12, 2008. No comments were received.						
CONTACTS AND MAILING LIST: TCEQ Attorney/SEP Coordinator: Ms. Melissa Keller, SEP Coordinator, Enforcement Division, MC 219, (512) 239-1768 TCEQ Enforcement Coordinator: Mr. Jorge Ibarra, P.E., Enforcement Division, Enforcement Team 3, MC R-04, (817) 588-5890; Mr. Bryan Sinclair, Enforcement Division, MC 219, (512) 239-2171 Respondent: CT Corporation System, Registered Agent, Valero Refining-Texas, L.P., 1021 Main Street, Suite 1150, Houston, Texas 77002 Mr. Adrian Araiza, Manager, Environmental Affairs, Valero Refining-Texas, L.P., P.O. Box 3429, Texas City, Texas 77592-3492 Respondent's Attorney: Not represented by counsel on this enforcement matter						

RESPONDENT NAME: Valero Refining-Texas, L.P.

DOCKET NO.: 2007-2039-AIR-E

VIOLATION SUMMARY CHART: CORRECTIVE ACTIONS OF A PENALTY CONSIDERATIONS **VIOLATION INFORMATION** TAKEN/REQUIRED **Ordering Provisions:** Type of Investigation: Total Assessed: \$10,000 ___ Complaint 1) The Order will require the Respondent Routine Total Deferred: \$2,000 to implement and complete a Enforcement Follow-up X Expedited Settlement Supplemental Environmental Project X Records Review (SEP). (See SEP Attachment A) Financial Inability to Pay Date(s) of Complaints Relating to this 2) The Order will also require the Case: None SEP Conditional Offset: \$4,000 Respondent to: **Date of Investigation Relating to this** Total Paid to General Revenue: \$4,000 a. Within 30 days after the effective date of Case: November 28, 2007 this Agreed Order, develop and implement Site Compliance History Classification measures to improve design, operations, Date of NOV/NOE Relating to this Case: High X Average Poor and/or maintenance practices to prevent December 5, 2007 (NOE) the reoccurrence of events similar to the **Person Compliance History Classification** emission events that occurred on Background Facts: This was a routine High X Average Poor September 27, 2007; and record review. Major Source: X Yes No b. Within 45 days after the effective date AIR of this Agreed Order, submit written Applicable Penalty Policy: September 2002 certification and include detailed Failed to maintain an emission rate below supporting documentation including the maximum allowable emission limits photographs, receipts, and/or other records from Boiler 27 [emission point number to demonstrate compliance with Ordering ("EPN EB-27")], Boiler 28 ("EPN EB-Provision 2.a. 28"), No. 1 Flare Stack ("EPN EFL-01"), No. 2 Flare Stack ("EPN EFL-02"), No. 3 Flare Stack ("EPN EFL-03"), and No. 4 Flare Stack ("EPN EFL-04"). Specifically, 1,730 pounds ("lbs") of volatile organic compounds, 890.7 lbs of sulfur dioxide, 86.9 lbs of nitrogen oxides, 18.5 lbs of carbon dioxide, and 10 lbs of hydrogen sulfide were emitted on September 27, 2007 in a 2 hour, 1 minute period [30 Tex. ADMIN. CODE § 116.715(a), Permit No. 39142, Special Condition No. 1, and TEX. HEALTH & SAFETY CODE § 382.085(b)].

Additional ID No(s).: GB0073P

Attachment A Docket Number: 2007-2039-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent:

Valero Refining-Texas, L.P.

Payable Penalty Amount:

Eight Thousand Dollars (\$8,000)

SEP Amount:

Four Thousand Dollars (\$4,000)

Type of SEP:

Pre-approved

Third-Party Recipient:

Houston-Galveston AERCO's Clean Cities/Clean Vehicles

Program

Location of SEP:

Galveston County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative Penalty Amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

A. Project

The Respondent will contribute to Houston-Galveston AERCO's Clean Cities/Clean Vehicles Program in Galveston County. The contribution will be used in accordance with the Supplemental Environmental Project Agreement between the Houston-Galveston AERCO and the Texas Commission on Environmental Quality. SEP monies will be used to aid local school districts and area transit agencies in reaching local match requirements mandated by the Federal Highway Administration's ("FHWA") Congestion Mitigation/Air Quality funding program. SEP monies will be disbursed to school districts and transit agencies in need of funding assistance in the Houston-Galveston non-attainment area. Those SEP monies will be used exclusively by the school districts and transit agencies as supplements to meet the local match requirements of the EPA. SEP monies will be used to pay for the cost of replacing older diesel buses with alternative fueled or clean diesel buses. The old buses will be permanently retired and only sold for scrap. The schools and transit agencies will also use the SEP monies to retrofit more buses to reduce emissions. Houston-Galveston AERCO will send the TCEQ verification in the form of paid invoices and other documentation to show that the retrofits were completed. Retrofit technologies include particulate matter traps, diesel particulate matter filters, NOx reduction catalyst technology in combination with diesel particulate filters, and other emission control technologies that are developed and approved by EPA or the California Air Resources Board.

The Respondent certifies that there is no prior commitment to do this project and that it is being performed solely in an effort to settle this enforcement action.

Valero Refining-Texas, L.P. Agreed Order - Attachment A

B. Environmental Benefit

This SEP will provide a discernible environmental benefit by reducing particulate emissions on buses by more than 90% below today's level and reducing hydrocarbons below measurement capability.

C. Minimum Expenditure

The Respondent shall contribute at least the SEP Amount to the Third-Party Recipient and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Amount to the Third-Party Recipient. The Respondent shall mail the contribution, with a copy of the Agreed Order, to:

Houston-Galveston Area Council Houston-Galveston ABRCO P.O. Box 22777 Houston, Texas 77227-2777

3. Records and Reporting

Concurrent with the payment of the SEP Amount, the Respondent shall provide the TCEQ SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Amount to the Third-Party Recipient. The Respondent shall mail a copy of the check and transmittal letter to:

Enforcement Division
Attention: SEP Coordinator, MC 219
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this SEP in any way, including full payment of the SEP Amount and submittal of the required reporting described in Section 3 above, the Executive Director may require immediate payment of all or part of the SEP Amount.

The check for any amount due shall be made out to "Texas Commission on Environmental Quality" and mailed to:

Texas Commission on Environmental Quality Financial Administration Division, Revenues Attention: Cashier, MC 214 P.O. Box 13088 Austin, Texas 78711-3088

and the second of the second

and the second second

the contract of the second of

en de la companya de la co La companya de la companya del companya del companya de la companya del la companya de la companya Valero Refining-Texas, L.P. Agreed Order - Attachment A

The Respondent shall also mail a copy of the check to the TCEQ SEP Coordinator at the address in Section 3 above.

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent must include a clear statement that the project was performed as part of the settlement of an enforcement action brought by the TCEQ. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP identified in this Agreed Order has not been, and shall not be, included as an SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.

Policy Revision 2 (Sep	Penalty Calculation	n Worksheet (P	CW) PCW Revision No.	ovember 6, 2007
TGEO	ember 2002)		FOV Revision IV	overriber 6, 2007
DATES Assigned PCW	10-Dec-2007 Screening 20-Dec-2007	EPA Due 31-Aug-2008		
DECDONDENT/EACH ITY	INFORMATION		- T-	
RESPONDENT/FACILITY	Valero Refining-Texas, L.P.			
Reg. Ent. Ref. No.		The state of the s	· · · · · · · · · · · · · · · · · · ·	
Facility/Site Region		Major/Minor Source	Major	AND
CASE INFORMATION				
Enf./Case ID No.	35136	No. of Violations	1	
	2007-2039-AIR-E	Order Type	1660	1.2
Media Program(s)	Air	Enf. Coordinator	Jorge Ibarra, P.E.	- T
Multi-Media		EC's Team	Enforcement Team 3	
Admin. Penalty \$ I	_imit Minimum \$0 Maximum	\$10,000		
	Penalty Calcula	ation Section	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
TOTAL BASE PENAL	TY (Sum of violation base penaltie	The second secon	Subtotal 1	\$5,000
				Madillar etak 1281 ya
ADJUSTMENTS (+/-) Subtotals 2-7 are obtain	TO SUBTOTAL 1 ned by multiplying the Total Base Penalty (Subtotal 1) by	the indicated percentage		
Compliance Histo			otals 2, 3, & 7	\$13,850
r gagar i i ar escribilitation sono con contra de la contra del contra de la contra del la contra de la contra de la contra del la contra del la contra de la contra del la contra	The Respondent was issued 19 NOVs wit			
	violations, three NOVs without the same/sii			
Notes	Court Order, three 1660 Agreed Orders, two			
	reported 18 months of efflue			
	reported to months of childe	THE VIOLATION S.	•	
Culpability	No 0%	Enhancement	Subtotal 4	\$0
		Specification and the second s]	
Notes	The Respondent does not meet the	e culpability criteria.		
	Appropriate to the second seco		! 	
Good Faith Effor	The state of the s	Reduction	Subtotal 5	\$0
_, .	Before NOV NOV to EDPRP/Settlement Offer		•	
Extraordinary Ordinary				
N/A	X (mark with x)			
2	A I (mark.widi x)]	
Notes	The Respondent does not meet the	e good faith criteria.		
A BARA SA				
		Enhancement*	Subtotal 6	\$0
		at the Total EB \$ Amount	· · · · · · · · · · · · · · · · · · ·	
Approx.	Cost of Compliance \$5,000			
SUM OF SUBTOTALS	9 1.7		Final Subtotal	\$18,850
SOW OF SUBTOTAL			-mai Subiolai	Ψ10,030
OTHER EACTORS AS	S JUSTICE MAY REQUIRE	0%	Adjustment	\$0
	ubtotal by the indicated percentage.	U 76	Aujustillent	Ψ0
Notes				
		Final Per	nalty Amount	\$18,850
. <u>La cidido de la cida de la cidade d</u> e la cidade de la cidade del cidade de la cidade del cidade de la cidade del cidade de la cidade de la cidade del cidade del cidade de la cidade del cid			sala covern revenues	
STATUTORY LIMIT A	DJUSTMENT	Final Asse	ssed Penalty	\$10,000
BEEEBB				Ac
DEFERRAL	olly by the indicted percentage (Cater number 1	20% Reduction	Adjustment	-\$2,000
reduces the Final Assessed Pen	alty by the indicted percentage. (Enter number only; e.g	g. 20 IOI 20% reduction.)	1	
Notos	Deferral offered for expedite	d cattlament		
Notes	Deletial offered for expediter	a semement.		
			J	
ΡΔΥΔΒΙ Ε ΡΕΝΔΙ ΤΥ				\$8,000

Screening Date 20-Dec-2007

Docket No. 2007-2039-AIR-E

PCW

Respondent Valero Refining-Texas, L.P.

Case ID No. 35136

Reg. Ent. Reference No. RN100238385

Media [Statute] Air

Enf. Coordinator Jorge Ibarra, P.E.

Policy Revision 2 (September 2002)
PCW Revision November 6, 2007

Compliance History Worksheet

Component	Number of	nter Number Here	Adjust
NOVs	Written NOVs with same or similar violations as those in the current enforcement action (number of NOVs meeting criteria)	19	95%
	Other written NOVs	21	42%
	Any agreed final enforcement orders containing a denial of liability (number of orders meeting criteria)	3	60%
Orders	Any adjudicated final enforcement orders, agreed final enforcement orders without a denial of liability, or default orders of this state or the federal government, or any final prohibitory emergency orders issued by the commission	2	50%
Judgments	Any non-adjudicated final court judgments or consent decrees containing a denial of liability of this state or the federal government (number of judgements or consent decrees meeting criteria)	1	30%
and Consent Decrees	Any adjudicated final court judgments and default judgments, or non-adjudicated final court judgments or consent decrees without a denial of liability, of this state or the federal government		0%
Convictions	Any criminal convictions of this state or the federal government (number of counts)	, 0	0%
Emissions	Chronic excessive emissions events (number of events)	0	0%
Audits	Letters notifying the executive director of an intended audit conducted under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which notices were submitted)	0	0%
	Disclosures of violations under the Texas Environmental, Health, and Safety Audit Privilege Act, 74th Legislature, 1995 (number of audits for which violations were disclosed)	0	0%
	Plea Plea	se Enter Yes or No	
- 1	Environmental management systems in place for one year or more	No	0%
Other	Voluntary on-site compliance assessments conducted by the executive director under a special assistance program	No	0%
	Participation in a voluntary pollution reduction program	No	0%
	Early compliance with, or offer of a product that meets future state or federal government environmental requirements	No	0%

Adjustment Percentage (Subtotal 2) 277%

>> Repeat Violator (Subtotal 3)

No

Adjustment Percentage (Subtotal 3)

0%

>> Compliance History Person Classification (Subtotal 7)

Average Performer

Adjustment Percentage (Subtotal 7)

0%

>> Compliance History Summary

Compliance History Notes The Respondent was issued 19 NOVs with the same/similar type of violations, three NOVs without the same/similar type of violations, one Court Order, three 1660 Agreed Orders, two Findings Orders, and self-reported 18 months of effluent violations.

Total Adjustment Percentage (Subtotals 2, 3, & 7)

277%

Screening Da	te 20-Dec-2007	Docket No. 2007-2039-AIR-E	PCW
환경 2 기업 명단 기업 전 경험 기업 등 중점 기업 명단	nt Valero Refining-Texa	s, L.P.	Policy Revision 2 (September 2002)
Case ID N			PCW Revision November 6, 2007
Reg. Ent. Reference N			
Media [Statut			
Ent. Coordinate	or Jorge Ibarra, P.E.		
			
Rule Cite	s) 30 Tex. Admin. Cod	de § 116.715(a), Permit No. 39142, Special Condition No. 1, Tex. Health & Safety Code § 382.085(b)	and
Violation Description	Boiler 27 [emission p Stack ("EPN EFL-01" 03"), and No. 4 Fla volatile organic con	e emission rate below the maximum allowable emission limits oint number ("EPN EB-27")], Boiler 28 ("EPN EB-28"), No. 1), No. 2 Flare Stack ("EPN EFL-02"), No. 3 Flare Stack ("EPN are Stack ("EPN EFL-04"). Specifically, 1,730 pounds ("Ibs") npounds, 890.7 lbs of sulfur dioxide, 86.9 lbs of nitrogen oxidoxide, and 10 lbs of hydrogen sulfide were emitted on Septe 27, 2007 in a 2 hour, 1 minute period.	Flare N EFL of des,
		Base Pe	enalty \$10,000
>> Environmental, Property	and Human Health	Matrix	
	Harı	m	
Relea OR Actu		rate Minor	
Potent		Percent 50%	and the second s
>>Programmatic Matrix			
Falsification	n Major Modei	rate Minor	***************************************
		Percent 0%	44.7
	sed to significant amour	n the Houston-Galveston-Brazoria ozone nonattainment areants of pollutants which did not exceed levels that are protection invironmental receptors as a result of the violation.	
2.0		Adjustment \$	5,000
			\$5,000
			ψ3,000
Violation Events	121 28 41		
Number of	Violation Events 1	Niverban of the latin of the la	
Number of	Violation Events 1	Number of violation days	
	daily		
•	monthly x		<u></u>
mark only on with an x		Violation Base Pe	enalty \$5,000
	semiannual		
	single event		
· F			
	One	e monthly event is recommended.	
Economic Benefit (EB) for	this violation	Statutory Limit Test	
Estima	ted EB Amount	\$233 Violation Final Penalty	Total \$18,850
_011114			
		This violation Final Assessed Penalty (adjusted for I	imits) \$10,000

1 42 APR 1 47 KANDARA 2010 2010 2010 201		conomic	Benefit W	orks	sheet	DATE:	
Respondent	Valero Refining	-Texas, L.P.	The state of the s	- lan all fall the Control on the	en elektrische Ausgeber V. Kanadische Ausgeber von der	a commission and a commission and a commission of the commission o	CONTRACTOR
Case ID No.	35136				7.11	And a second	
Reg. Ent. Reference No.	RN100238385					Brana Kara S	. 636
Media	Air					Percent Interest	Years of
Violation No.	1					Fercent interest	Depreciation
	131 D. L.	ake milotu. Kuli	474-E-14	120	there is a construction	5,0	1:
Salitina de	Item Cost	Date Required	Final Date	Yrs	Interest Saved	Burney and providence of the second contract of the second	EB Amount
100.41	Q.65 M. 205. Sec.	Date Required	rillai Dale	4 7 4 7 7		Ciletime Gosta	ED WIIIOUIT
Item Description	No commas or \$	era i Çer ana yeraz			inger (1944)		職権に対すると
, ASS	epimacjimoropowia wajawa to waza	and the second s	i i koles el diskonintakon matakasa	k isasakapan	o seko zakonoka a ukaza je	s o a maria de la compansión de la compa	est the first section of
Delayed Costs				4 44 6			a de la companya de
Equipment	Charles and the contract of th			0,0	\$0	\$0	\$0
Buildings				0.0	\$0	\$0	\$0
Other (as needed)				0,0	\$0	\$0 00	\$0
Engineering/construction				0.0	\$0	\$0	\$0
Land				0.0	\$0 \$0	n/a	\$0 IleiV \$0
Record Keeping System			1.7 (1.7 (1.4 (1.4 (1.4 (1.4 (1.4 (1.4 (1.4 (1.4	0.0	\$0 \$0	n/a	
Training/Sampling		and the state of t	232255566	0.0 0.0	\$0 \$0		\$0 \$0
Remediation/Disposal Permit Costs	Service and the service of the servi	Liber Constitution and Constitution Con-		0.0	\$0	n/a n/a	\$0 \$0
Other (as needed)	\$5,000	27-Sep-2007	1-Sep-2008	0.9	\$233	n/a	\$233
e e	Estimated co	st to maintain an e	mission rate belov	the ma	ximum allowable	emission limits and t	o develop and
Notes for DELAYED costs	implement mea	asures to improve	design, operations	, and/or	maintenance prac	emission limits and to stices to prevent the e is the expected co	reoccurrence c
+ 11.881,112	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	, and/or emissior	maintenance prac n event. Final Dat	tices to prevent the	reoccurrence o mpliance date.
Notes for DELAYED costs Avoided Costs Disposal	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	, and/or emissior	maintenance prac n event. Final Dat	etices to prevent the e is the expected co	reoccurrence o mpliance date.
Avoided Costs	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	, and/or emission ntering 0.0	maintenance practice term (except for \$0 \$0	etices to prevent the e is the expected co one-time avoided co \$0 \$0	reoccurrence o mpliance date. costs) \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	, and/or emission ntering 0.0 0.0	maintenance practice the second event. Final Data litem (except for \$0 \$0 \$0	ctices to prevent the e is the expected co	reoccurrence o mpliance date. costs) \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0	maintenance prace nevent. Final Date	ctices to prevent the e is the expected coone-time avoided (reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment Financial Assurance [2]	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	maintenance practice of the second event. Final Data litem (except for \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	ctices to prevent the e is the expected co	reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment Financial Assurance [2] ONE-TIME avoided costs [3]	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.	maintenance prace nevent. Final Date So So So So So So So S	ctices to prevent the e is the expected co	reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment Financial Assurance [2]	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0	maintenance practice of the second event. Final Data litem (except for \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	ctices to prevent the e is the expected co	reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment Financial Assurance [2] ONE-TIME avoided costs [3]	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.	maintenance prace nevent. Final Date So So So So So So So S	ctices to prevent the e is the expected co	reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Avoided Costs Disposal Personnel Inspection/Reporting/Sampling Supplies/equipment Financial Assurance [2] ONE-TIME avoided costs [3] Other (as needed)	implement mea emission ever	asures to improve nts. Date Required	design, operations is the date of the	ntering 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.	maintenance prace nevent. Final Date So So So So So So So S	ctices to prevent the e is the expected co	reoccurrence of mpliance date. costs) \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0

Compliance History

Customer/Resp	ondent/Owner-Operator:	CN600127468	Valero Refining-Texas, L.P		Classification: AVERAGE	Rating: 6.12	
Regulated Entity	<i>r</i> :	RN100238385	VALERO REFINING TEXA	AS CITY	Classification: AVERAGE	Site Rating: 5.2	8
ID Number(s):		AIR OPERATING		ACCOUNT	NUMBER	GB0073P	
		AIR OPERATING	PERMITS	PERMIT		1253	
		**					
		AIR OPERATING		PERMIT		2599	
		AIR OPERATING	PERMITS	PERMIT		2599	
		WASTEWATER		PERMIT		TPDES0006009	
		WASTEWATER		PERMIT		WQ0000449000	
		WASTEWATER		PERMIT		TX0006009	
		AIR NEW SOURCE	CE PERMITS	PERMIT	,	39142	
		AIR NEW SOURC		PERMIT			
			,			42395	
		AIR NEW SOURC		PERMIT		42394	
		AIR NEW SOURC	E PERMITS	PERMIT		48330	
		AIR NEW SOURC	E PERMITS	ACCOUNT	NUMBER	GB0073P	
	•	AIR NEW SOURCE	E PERMITS	PERMIT		962	
		AIR NEW SOURC		PERMIT		8352	
		AIR NEW SOURC		PERMIT		8617A	
		AIR NEW SOURC	E PERMITS	PERMIT		53530	
		AIR NEW SOURC	E PERMITS	EPA ID		PSDTX822	
		AIR NEW SOURC	E PERMITS	AFS NUM		4816700007	7
		AIR NEW SOURCE		EPA ID		PSDTX822M2	
		AIR NEW SOURC		PERMIT		71076	
		AIR NEW SOURC		REGISTRAT	ION	75542	
		AIR NEW SOURC	E PERMITS	. REGISTRAT	TION	75695	
		AIR NEW SOURC	E PERMITS	REGISTRAT	rion	72517	
		AIR NEW SOURC		REGISTRAT		73799	
						and the second s	
		AIR NEW SOURC		REGISTRAT		76530	
		AIR NEW SOURC		REGISTRAT	JON	76967	
		AIR NEW SOURC	E PERMITS	REGISTRAT	TION	77806	271
		AIR NEW SOURC	E PERMITS	REGISTRAT	TION	79850	
		AIR NEW SOURC	F PERMITS	REGISTRAT		79881	
		AIR NEW SOURC	*				
			A Committee of the Comm	REGISTRAT		80132	
		AIR NEW SOURC		REGISTRAT	TON	80059	
		AIR NEW SOURC	E PERMITS	REGISTRAT	TION	80581	150
		AIR NEW SOURC	E PERMITS	REGISTRAT	ION	81005	
		AIR NEW SOURC	F PERMITS	REGISTRAT		81523	
		AIR NEW SOURC	· ·	REGISTRAT			
						81621	
		AIR NEW SOURC		REGISTRAT		81695	
		AIR NEW SOURC	E PERMITS	REGISTRAT	ION	82055	
		AIR NEW SOURC	E PERMITS	REGISTRAT	TON	82462	
		AIR NEW SOURC	E PERMITS	REGISTRAT	TON	82434	
	·	AIR NEW SOURC					
				REGISTRAT		82433	
			HAZARDOUS WASTE		TE REGISTRATION #	30011	
		GENERATION		(SWR)			
			HAZARDOUS WASTE	EPA ID		TXD000792937	
		GENERATION					
		WASTE WATER O	SENERAL PERMIT	PERMIT	The second secon	TXG670007	
Location:		1301 LOOP 197 S,	TEXAS CITY, TX, 77590		Rating Date: September 01 (07 Repeat Violator:	
TCEQ Region:		REGION 12 - HOU	STON			-	
Date Compliance	e History Prepared:	December 13, 200	7				
Agency Decision	Requiring Compliance History:	Enforcement					
Compliance Peri	od:	December 13, 2002	2 to December 13, 2007	4			
TCEQ Staff Mem	ber to Contact for Additional Inforn	nation Regarding this (Compliance History	•			
Name:	Jorge Ibarra, P.E.	Pho				1	
	10-11-11-11-11-11-11-11-11-11-11-11-11-1				•		
A Harris W. S.			Compliance History Comp	onents			
1. Has the site be	een in existence and/or operation fo	or the full five year con	npliance period?	Yes			
2. Has there bee	n a (known) change in ownership c	of the site during the co	empliance period?	No			
	the current owner?	•	•	N/A	•		
				-		_	

5. When did the change(s) in ownership occur?

Components (Multimedia) for the Site:

Final Enforcement Orders, court judgements, and consent decrees of the state of Texas and the federal government.

Effective Date: 03/11/2005

ADMINORDER 2002-1217-IWD-E

N/A

Classification: Moderate

2D TWC Chapter 26, SubChapter A 26.121(a)

30 TAC Chapter 305, SubChapter F 305.125(1)

Rgmt Prov:

Effluent Limitations and Monitoring Reqs PERMIT

Description: Failure to comply with the WET limit NOEC of 8% effluent specified in the permit.

Effective Date: 11/23/2005

COURTORDER

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

39142, Special Condition No. 1 PA

Description: Exceeded permit limit during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter A 382.085(b)

39142, Special Condition No. 1 PA

Ramt Prov: Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov:

39142/PSDTX822M2, SC#1 PERMIT

Description: Failed to prevent a leak in a heat exchanger (E-1338).

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

TCEQ Flexible Air Permit #39142, SC #1 PERMIT

Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

39142/ PSD-TX-822M2 PERMIT

Description: Valero failed to prevent a back-up pump from tripping off.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

TCEQ Flexible Air Permit #39142, SC #1 PERMIT Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

39142, SC No. 1 PA

Description: Exceeded permit limit during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

TCEQ Flexible Air Permit #39142, SC #1 PERMIT

Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

TCEQ Flexible Air Permit #39142, SC #1 PERMIT

Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

5C THC Chapter 382, SubChapter A 382.085(a)

Description: Failed to prevent an avoidable emissions event.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter B 116.110(a)(1)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failed to prevent an avoidable emissions event.

Effective Date: 10/19/2006 ADMINORDER 2006-0549-IWD-E

Classification: Moderate

Citation: 2D TWC Chapter 26, SubChapter A 26.121(a)

30 TAC Chapter 305, SubChapter F 305.125(1)

Rqmt Prov: Effluent Limits PERMIT

Description: Failure to comply with permit effluent limits as documented by a TCEQ record review of

self-reported data.

Effective Date: 05/11/2007 ADMINORDER 2006-0012-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 117, SubChapter E 117.520(c)(2)(A)(i)

5C THC Chapter 382, SubChapter A 382.085(b)

Description: Failure to install continuous emissions monitoring systems ("CEMS") on boilers B-07 and

B-11 by March 31, 2005.

Effective Date: 08/23/2007 ADMINORDER 2006-1067-AIR-E

Classification: Moderate

Citation: 30 TAC Chapter 112, SubChapter B 112.31

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter A 382.085(b)

Rgmt Prov: TCEQ Flexible Air Permit No. 39142, SC1 PERMIT

Description: As evidenced by Findings of Fact No. 12, Valero failed to prevent unauthorized emissions that exceeded the fence line H2S concentration limit during an emissions event that started on October 4,

2004.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter D 382.085(b)

Rgmt Prov: 39142, SC No. 1 PA

Description: Failure to prevent an overpressure condition resulting in unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: 39142, SC No. 1 PA

Description: Failure to prevent a control valve malfunction resulting in unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter D 382.085(b)

Rgmt Prov: 39142, SC No. 1 PA

Description: Failure to maintain calibration of a level indicator resulting in unauthorized emissions.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(c)

5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to submit final report no later than two weeks after end of emissions event.

Classification: Minor

Citation: 30 TAC Chapter 101, SubChapter F 101.201(c)

5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to submit a final report no later than two weeks after the end of an emissions event.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: 39142, SC No. 1 PA

Description: Failure to prevent a control valve malfunction resulting in unauthorized emissions.

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter D 382.085(b)

Rgmt Prov: 39142 SC No. 1 PA

Description: Failure to prevent a control valve malfunction resulting in unauthorized emissions

Classification: Moderate

Citation: 30 TAC Chapter 101, SubChapter A 101.20(3)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov: 39142, SC No. 1 PA

Description: Failure to prevent a tank overflow resulting in unauthorized emissions.

Classification: Minor

Citation:

30 TAC Chapter 101, SubChapter F 101.201(b)(1)(H)

5C THC Chapter 382, SubChapter D 382.085(b)

Description: Failure to provide preconstruction authorization number on final report.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

39142, SC 1 PA

Description: Exceeded permit limits during an avoidable emissions event.

Classification: Moderate

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Ramt Prov:

39142, SC No. 1 PA

Description: Exceeded permit limits during an avoidable emissions event.

Effective Date: 11/19/2007

ADMINORDER 2006-0468-MLM-E

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

No. 39142, SC No. 1 PA

Description: Failed to prevent unauthorized emissions from Flare Nos. 2 and 3 (EPN EFL-02 and EFL-03) during an emissions event which occurred on October 13, 2005 in the Utilities Unit and lasted 2 hours and 15 minutes, as documented during a record review conducted on February 8, 2006. Since this emissions event was avoidable, Valero failed to meet the demonstrations for an affirmative defense in 30 TEX.

ADMIN. CODE § 101.222. Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

39142, SC No. 1 PA

Description: Failed to prevent unauthorized emissions from Flare Nos. 2, 3 and 4 (EPN EFL-02, EFL-03 and EFL-04) during an emissions event which occurred on November 28, 2005 in the Utilities Unit and lasted 24 hours and 29 minutes, as documented during a record review conducted on January 25, 2006. Since this emissions event was avoidable, Valero failed to meet the demonstrations for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

No. 39142, SC No. 1 PA Ramt Prov:

Description: Failed to prevent unauthorized emissions from the Incinerator Stack (EPN EG-18-1403) during an emissions event which occurred on September 20, 2005 in the Gas-Oil Hydrotreater (GOHT) Unit (PRU) and lasted 55 hours, as documented during an investigation conducted on November 29, 2005. Since this emissions event was avoidable, Valero failed to meet the demonstrations for an affirmative defense in 30 TEX. ADMIN. CODE § 101.222.

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Rgmt Prov:

Description: Failed to prevent unauthorized emissions during a September 25, 2006 emissions event, as documented during a record review conducted on November 29, 2006. Specifically, during the September 25, 2006 emissions event the following unauthorized emissions were released from the No. 2 and No. 3 Flare over a period of fifty-five minutes: 2,101 lbs of sulfur dioxide, 328.5 lbs of volatile organic compounds, 191 lbs of carbon monoxide, and 26.4 lbs of nitrogen oxides.

Classification: Moderate

Citation:

30 TAC Chapter 101, SubChapter A 101.20(1)

30 TAC Chapter 116, SubChapter G 116.715(a)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)

5C THC Chapter 382, SubChapter D 382.085(b)

39142, SC No. 1 PA Ramt Prov:

Description: Failed to prevent unauthorized emissions and failure to operate a flare with a flame present during an October 14, 2006 emissions event, as documented during a record review conducted on December 13, 2006. Specifically, on October 14, 2006 through October 15, 2006, over a period of 4 hours and 14 minutes, Flare No. 3 (EPN EFL-03) located in the Utilities Unit, emitted 1,333.4 lbs of ethylene and 1,394.5 lbs of propane. Flexible Air Permit No. 39142 does not authorize any upset emissions.

Any criminal convictions of the state of Texas and the federal government.

N/A

B.

Chronic excessive emissions events. C.

```
1 12/20/2002
                   (158520)
 2 01/16/2003
                   (17965)
 3 01/21/2003
                   (158524)
 4 01/31/2003
                   (21539)
 5 02/13/2003
                   (24351)
 6 02/18/2003
                   (158482)
 7
   02/24/2003
                   (6655)
 8 03/24/2003
                   (158485)
 9 04/16/2003
                   (24233)
10 04/16/2003
                   (24831)
11 04/21/2003
                   (158490)
12 05/06/2003
                   (27702)
13
   05/09/2003
                   (35604)
14
   05/23/2003
                   (158494)
15
   05/27/2003
                   (35847)
16
   05/27/2003
                   (34689)
17 05/27/2003
                   (35995)
18 05/27/2003
                  (34681)
19 05/28/2003
                  (34893)
20 05/30/2003
                   (37806)
21 05/30/2003
                   (37838)
22 05/30/2003
                   (37791)
23 06/19/2003
                   (36509)
24 06/19/2003
                   (36515)
25 06/24/2003
                   (158506)
26
   06/24/2003
                   (158498)
27
   06/25/2003
                   (37826)
28
   06/25/2003
                   (35521)
29 07/02/2003
                   (60623)
30 07/22/2003
                  (158502)
31 08/06/2003
                  (143528)
32 08/19/2003
                  (148080)
33 08/23/2003
                   (60572)
34 08/25/2003
                  (143078)
35 08/28/2003
                  (149898)
36 09/25/2003
                   (295526)
   10/16/2003
37
                  (152454)
   10/16/2003
                  (152211)
39
   10/21/2003
                   (250278)
40
   10/23/2003
                   (295528)
41 11/21/2003
                  (295529)
42
   12/29/2003
                   (295530)
   12/29/2003
43
                  (295532)
44 02/23/2004
                   (295513)
45 02/25/2004
                   (261619)
46
   02/27/2004
                   (263268)
47
   02/29/2004
                   (251270)
48
   03/02/2004
                   (254943)
49
   03/10/2004
                   (261338)
50
   03/16/2004
                   (265447)
51
   03/16/2004
                   (261251)
52 03/19/2004
                   (295517)
53 04/21/2004
                  (295518)
54 05/20/2004
                  (295520)
55 05/21/2004
                   (268720)
56 05/21/2004
                   (268709)
57 06/02/2004
                   (268446)
58 06/11/2004
                   (270014)
   06/17/2004
                  (295522)
59
60
   06/18/2004
                   (272120)
61
   07/02/2004
                  (272940)
62
   07/02/2004
                   (271086)
63
   07/02/2004
                   (271249)
   07/02/2004
                  (272143)
64
```

07/02/2004

66 07/05/2004

(271833)

(271296)

		(070050)
67	07/16/2004 07/20/2004	(272858)
68 69	07/20/2004	(273783) (257997)
70	07/26/2004	(352180)
71	07/20/2004	(274385)
72	07/30/2004	(278540)
73	07/30/2004	(274350)
74	08/03/2004	(286886)
75	08/04/2004	(276497)
76	08/06/2004	(258328)
77	08/13/2004	(261714)
78	08/13/2004	(261538)
79	08/16/2004	(282158)
80	08/16/2004	(280377)
81	08/17/2004	(289843)
82	08/17/2004	(258260)
83	08/24/2004	(352181)
84	08/28/2004	(264976)
85	08/31/2004	(268711)
86	08/31/2004	(269258)
87	08/31/2004	(270855)
88	08/31/2004	(271300)
89	09/01/2004	(291403)
90	09/01/2004	(289773)
91	09/15/2004	(334014)
92	09/23/2004	(352182)
93	10/19/2004	(334137)
94	10/22/2004	(352183)
95	10/27/2004	(289067)
96	11/11/2004	(281257)
97	11/12/2004	(281637)
98	11/12/2004	(283676)
99	11/12/2004	(281714)
100	11/12/2004	(281823)
101	11/15/2004	(337390)
102	11/18/2004	(352184)
103	12/10/2004	(285390)
103	12/13/2004	(340262)
105	12/13/2004	(290035)
106	12/14/2004	(281320)
107	12/14/2004	(334546)
108	12/14/2004	(338676)
109	12/14/2004	(334780)
110	12/16/2004	(281398)
111	12/16/2004	(283937)
112	12/17/2004	(338870)
113	12/20/2004	(381870)
114	12/20/2004	(281999)
115	12/23/2004	(339913)
116	12/28/2004	(281856)
117	01/03/2005	(281991)
118	01/03/2005	(282000)
119	01/04/2005	(281998)
120	01/04/2005	(338922)
121	01/04/2005	(346230)
122	01/06/2005	(285581)
123	01/10/2005	(339417)
123	01/10/2005	(339003)
	01/10/2005	(281993)
125	01/10/2005	(281997)
126	01/10/2005	(339012)
127	01/12/2005	(339012)
128	01/24/2005	(343619)
129		
130	01/31/2005	(285435)
131	02/14/2005	(274930)
132	02/22/2005	(381868)
133	03/22/2005	(381869)
134	03/31/2005	(350576)

eli jirgiri

HE FERENCE

LETTER

LE

135	04/25/2005	(419706)
136	04/26/2005	(343243)
137	04/26/2005	(281994)
		,
138	04/27/2005	(282002)
139	05/02/2005	(350537)
140	05/02/2005	(349631)
141	05/20/2005	(348483)
142	05/23/2005	(419707)
143	05/25/2005	(351133)
144	06/14/2005	(373350)
	06/14/2005	,
145		(378741)
146	06/14/2005	(419708)
147	06/23/2005	(378628)
148	06/27/2005	(397418)
149	06/28/2005	(348790)
150	06/30/2005	(397555)
151	07/07/2005	(399131)
152	07/13/2005	(399194)
153	07/15/2005	(348789)
154	07/22/2005	(440845)
155	07/22/2005	(397707)
156	08/02/2005	(348759)
157	08/03/2005	(403276)
158	08/03/2005	(403101)
159	08/08/2005	(403521)
160	08/08/2005	(403525)
161	08/10/2005	(396623)
162	08/13/2005	(400189)
163	08/13/2005	(397699)
164	08/17/2005	(400929)
165	08/18/2005	(406027)
166	08/19/2005	(396740)
167	08/22/2005	(406017)
168	08/23/2005	(440846)
169	08/24/2005	(400925)
170	08/29/2005	(406800)
171	09/01/2005	(400337)
	09/01/2005	, ,
172		(440847)
173	10/20/2005	(468457)
174	11/22/2005	(468458)
175,	12/06/2005	(438942)
176	12/20/2005	(468459)
177	12/28/2005	(449585)
178	12/29/2005	(439223)
. 179	12/29/2005	(449459)
180	01/17/2006	(431818)
181	01/24/2006	(468460)
182		(440131)
	01/30/2006	
183	02/01/2006	(451967)
184	02/15/2006	(439989)
185	02/17/2006	(468454)
186	02/17/2006	(439355)
187	02/21/2006	(455248)
188	03/16/2006	(455002)
189	03/21/2006	(468455)
190	03/29/2006	(453666)
191	03/31/2006	(434168)
192	04/13/2006	(468456)
	04/13/2006	
193		(457610)
194	04/27/2006	(460539)
195	05/08/2006	(453710)
196	05/11/2006	(461750)
197	05/15/2006	(462815)
198	05/17/2006	(464808)
199	05/18/2006	(498220)
200	05/25/2006	(457878)
201.	05/31/2006	(463733)
202	06/16/2006	(498221)
	-	/

203	06/27/2006	(481343)
204	06/30/2006	(483867)
205	06/30/2006	(462803)
206	06/30/2006	(481516)
207	06/30/2006	(462898)
208	07/06/2006	(482247)
209	07/14/2006	(486365)
210	07/15/2006	(486391)
211	07/17/2006	(479861)
		, ,
212	07/18/2006	(498222)
213	07/19/2006	(483715)
214	07/19/2006	(483638)
215	07/19/2006	(482178)
216	07/21/2006	(487892)
217	07/21/2006	(487175)
	07/21/2006	, ,
218		(487390)
219	07/25/2006	(488179)
220	07/26/2006	(462901)
221	07/26/2006	(482594)
222	08/10/2006	(520234)
223	08/25/2006	(488734)
224	09/01/2006	(509756)
225	09/01/2006	(488032)
226	09/01/2006	(488541)
227	09/01/2006	(489837)
228	09/01/2006	(489434)
229	09/01/2006	(487342)
230	09/01/2006	
		(489815)
231	09/01/2006	(466736)
232	09/01/2006	(488559)
233	09/01/2006	(488176)
234	09/01/2006	(488979)
235	09/01/2006	(509730)
236	09/01/2006	(478491)
237	09/01/2006	(488624)
238	09/01/2006	(478556)
239	09/01/2006	(488740)
240	09/01/2006	(488134)
241	09/01/2006	(490185)
	09/01/2006	(488020)
242		
243	09/01/2006	(508690)
244	09/01/2006	(488633)
245	09/01/2006	(489467)
246	09/01/2006	(488191)
247	09/01/2006	(509784)
248	09/01/2006	(466735)
249	09/01/2006	(478638)
250	09/01/2006	(489863)
251	09/01/2006	(509713)
252	09/01/2006	(487896)
253	09/01/2006	(509158)
254	09/01/2006	(489866)
	09/18/2006	. ,
255		(520235)
256	09/27/2006	(512555)
257	09/28/2006	(509876)
258	10/11/2006	(514061)
259	10/19/2006	(520236)
260	10/23/2006	(512981)
261	10/23/2006	(517239)
262	11/07/2006	(516594)
263	11/13/2006	(518837)
264	11/15/2006	(519473)
265	11/15/2006	(544546)
266	11/21/2006	(519775)
267	12/13/2006	(544547)
268	12/18/2006	(345058)
269	12/21/2006	(532369)
270	12/21/2006	(532370)

	271	01/16/2007	(534075)		
	272	01/19/2007	(532751)		
	273	01/19/2007	(544548)		
	274	02/07/2007	(536972)		
	275	02/09/2007	(534096)		
	276	02/14/2007	(544545)		
	277	03/15/2007	(531898)		
	278	03/15/2007	(575352)		
	279	03/15/2007	(533196)		
	280	03/23/2007	(543996)		
	281	04/02/2007	(539574)		
	282	04/05/2007	(543902)		
	283	04/09/2007	(555314)		
	284	04/09/2007	(543124)		
	285	04/10/2007	(543795)		
	286	04/11/2007	(556038)		
	287	04/11/2007	(556037)		
	288	04/17/2007	(575353)		
	289	04/30/2007	(557962)		
	290	04/30/2007	(556603)		
	291	04/30/2007	, ,		
	292	05/08/2007	(556624)		
	293		(555995)		
		05/10/2007	(559619)		
	294	05/10/2007	(559617)		
·	295	05/10/2007	(559620)		
	296	05/11/2007	(558768)		
	297	05/14/2007	(559618)		
	298	05/14/2007	(558769)		
	299	05/14/2007	(555999)		
	300	05/20/2007	(575354)		
	301	05/31/2007	(542320)		
	302	06/01/2007	(561100)		
	303	06/04/2007	(561098)		
	304	06/20/2007	(575355)		
	305	06/22/2007	(561101)		
	306	07/03/2007	(566302)		
	307	07/09/2007	(564575)		
	308	07/11/2007	(431249)		
	309	07/20/2007	(575356)		
	310	07/23/2007	(531864)		
	311	07/31/2007	(564508)		
	312	08/10/2007	(564206)		
	313	08/10/2007	(512666)		
	314	08/10/2007	(564225)		
	315	08/20/2007	(607555)		
	316	08/24/2007	(570707)		
	317	08/24/2007	(570706)		
	318	09/20/2007	(607556)		
	319	10/02/2007	(572268)		
	320	10/05/2007	(595008)		
	321	10/05/2007	(572254)		
	322	10/09/2007	(594109)		
	323	10/10/2007	(595720)		
	324	10/11/2007	(568182)		
	325	10/11/2007	(567830)		
	326	10/11/2007	(568141)		
	327	10/11/2007	(593936)		
	328	10/11/2007	(568234)		
	329	10/12/2007	(572190)		
	330	10/12/2007	(572204)		
	331	10/12/2007	(572244)		
	332	10/15/2007	(593466)		
	333	10/16/2007	(568501)		
	334	10/17/2007	(595009)		
	335	10/19/2007	(607557)		
	336	11/16/2007	(568445)		
	337	11/19/2007	(598398)		
	338	11/19/2007	(595089)		
			/		

(597629) 339 11/19/2007 340 11/19/2007 (571858) 341 11/19/2007 (597934)11/27/2007 (571671)342 (609936)343 12/05/2007

Written notices of violations (NOV). (CCEDS Inv. Track. No.) F

Date: 12/31/2002

(158524)

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1) TWC Chapter 26 26.121(a)

Description: Date: 01/31/2003

Citation:

Citation:

Failure to meet the limit for one or more permit parameter (158482)

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Classification:

Classification:

Classification:

Classification:

Classification:

Classification:

Classification:

Classification:

Classification:

Moderate

Moderate

Moderate

Moderate

Minor

Moderate

Minor

Moderate

Moderate

Moderate

Date: 04/30/2003

(158494)

Self Report?

Citation:

30 TAC Chapter 305, SubChapter F 305.125(1) TWC Chapter 26 26.121(a)

Description:

Citation:

Failure to meet the limit for one or more permit parameter (158502) Date: 06/30/2003

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter Description:

Date: 08/27/2003

Self Report?

30 TAC Chapter 101, SubChapter A 101.20(2) Citation: 30 TAC Chapter 115, SubChapter D 115.352(4)

30 TAC Chapter 116, SubChapter G 116.715(a)

40 CFR Chapter 63, SubChapter C, PT 63, SubPT H 63.167(a)

Ramt Prov: Description:

Citation:

PA 39412, SC 15E Non clerical air violation (295532)

(143078)

Date: 12/31/2003

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter

Description:

Date: 02/29/2004 (251270)

Self Report?

30 TAC Chapter 101, SubChapter F 101.201(b)(7) Citation:

Description:

(254943)Date: 03/02/2004

Self Report?

30 TAC Chapter 116, SubChapter G 116.715(a)

Citation:

5C THC Chapter 382, SubChapter A 382.085(b)

Valero failed to properly report an emissions event.

Ramt Prov:

PERMIT TCEQ FLEXIBLE AIR PERMIT 39142, SC #1

Description:

Valero exceeded permitted source emission limits during an avoidable emissions event.

NO Self Report?

30 TAC Chapter 101, SubChapter A 101.20(1) Citation:

40 CFR Chapter 60, SubChapter C, PT 60, SubPT A 60.18(c)(2)

Rqmt Prov:

PERMIT TCEQ FLEXIBLE AIR PERMIT SC #2(A)

Description: Date: 03/04/2004 (261689)

Self Report?

Valero operated Flare #4 with no flame present.

Classification: Moderate

Citation:

30 TAC Chapter 101, SubChapter A 101.4

Valero is in of violation for adversely affecting the normal use and enjoyment of Description:

property Date: 04/30/2004 (295520)

Self Report? YES

30 TAC Chapter 305, SubChapter F 305.125(1) Citation:

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter Description:

(257997)Date: 07/26/2004

Self Report?

Classification:

Classification:

Moderate

Citation:

30 TAC Chapter 101, SubChapter A 101.20(1)

30 TAC Chapter 116, SubChapter G 116.715(a)

40 CFR Chapter 60, SubChapter C, PT 60, SubPT J 60,104(a)(1)

Ramt Prov:

PERMIT Flexible Permit # 39142 and PSD TX-822M2 PERMIT Flexible Permit #39142 and PSD-TX-822M2

Description

Failure to maintain Coker fuel gas H2S concentration below 162 ppm on a

three-hour average basis.

Self Report? NO

Classification:

Citation: Rgmt Prov: 30 TAC Chapter 116, SubChapter G 116.715(a) PERMIT Flexible Permit # 39142 and PSD-TX-822M2

Description:

Failure to maintain Coker fuel gas H2S concentration below 162 ppm on a one

hour average basis.

Self Report?

30 TAC Chapter 101, SubChapter F 101.201(a)(1)

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

Rgmt Prov:

PERMIT Flexible Permit # 39142 and PSD-TX-822M2

Description:

Failure to report a reportable emission event which resulted in the release of H2S

and benzene emissions in excess of the reportable quantity.

Self Report? NO

Classification: Moderate

Classification:

Moderate

Moderate

Citation: Rqmt Prov: 30 TAC Chapter 116, SubChapter G 116.715(a) PERMIT Flexible Permit # 39142 and PSD-TX-822M2

Description:

failure to maintain the SRU thermal reactor with sour water overhead gas flow at a

flame temperature of 2000 degrees F or greater.

Failure to maintain the SRU thermal reactor with sour water overhead gas flow at

a flame temperature of 2000 degrees F or greater.

Date: 08/28/2004

(264976)

NO

Self Report?

Classification; Moderate

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b) PA Flexible Permit No. 39142, SC 1

Description:

Failure to prevent unauthorized emissions during an emissions event.

Date: 08/31/2004

(270855)Self Report?

Classification: Moderate

Citation:

Citation:

Rqmt Prov:

30 TAC Chapter 116, SubChapter G 116.715(a) PA Permit No. 39142 and PSD-TX-822M2, SC #1

Ramt Prov

Exceeded permit limits.

Description: Date: 08/31/2004

(271300)

(269258)

Self Report?

Classification: Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116,715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

PA Flexible Permit No. 39142, SC 1 Failure to prevent unauthorized emissions.

Description: Date: 08/31/2004

Self Report?

Classification: Moderate

Classification:

Classification:

Classification:

Moderate

Moderate

Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter A 382.085(b)

Rgmt Prov Description:

Citation:

PA Flexible Permit No. 39142, SC 1 Failure to prevent unauthorized emissions.

Date: 09/30/2004

(352183)

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Date: 12/10/2004

(285390)

Self Report?

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

Rgmt Prov:

5C THC Chapter 382, SubChapter A 382.085(b)

Description:

PA 39142 and PSD-TX-822M2

Failure to meet demonstration criteria.

Date: 12/28/2004

(281856)

(381871)

Self Report?

30 TAC Chapter 116, SubChapter G 116.715(a)

Citation: Rgmt Prov:

5C THC Chapter 382, SubChapter A 382.085(b)

PA 9142 and PSD-TX-822M2

Description:

Failure to meet demonstration criteria.

Date: 12/31/2004

Self Report? YES Classification: Moderate

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Date: 01/06/2005 (338922)

Classification: Self Report? Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(c)(7)

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

PA 39142, Special Condition No. 1

Description:

Failure to meet demonstration criteria.

Date: 01/31/2005

(285435)

Self Report?

30 TAC Chapter 116, SubChapter G 116.715(a)

Citation: 5C THC Chapter 382, SubChapter A 382.085(b)

(381869)

Ramt Prov: PA 39142, SC No. 1

Description:

Citation:

Failure to meet demonstration criteria.

Date: 02/28/2005

Self Report?

Classification:

Classification:

Classification:

Classification:

Classification:

Classification:

Moderate

Moderate

Moderate

Moderate

Moderate

Moderate

Moderate

30 TAC Chapter 305, SubChapter F 305.125(1) TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Date: 03/31/2005

Self Report? Citation:

30 TAC Chapter 305, SubChapter F 305.125(1)

(419706)

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter Description:

Date: 08/10/2005 (396623)

Self Report? 30 TAC Chapter 116, SubChapter G 116.715(a) Citation:

5C THC Chapter 382, SubChapter A 382.085(b)

Ramt Prov:

Citation:

PA 39142, Special Condition No. 1

Description:

Valero failed to control hydrocarbon carryover from the Delayed Coker Unit into

the Amine Unit.

Date: 10/31/2005 (468458)

Classification: Moderate Self Report? YES

30 TAC Chapter 305, SubChapter F 305.125(1) Citation:

TWC Chapter 26 26.121(a) Description: Failure to meet the limit for one or more permit parameter

Date: 11/30/2005 (468459)

Self Report?

Citation: 30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter Description:

12/31/2005 (468460)Date:

Classification: Self Report?

> 30 TAC Chapter 305, SubChapter F 305.125(1) TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter

Description:

Date: 01/31/2006 (451967)

Classification: Moderate Self Report?

Citation: TWC Chapter 26 26.121(a)(1)

PERMIT No. 00449-000 Page 7, No. 2g Ramt Prov: Description: Failure to prevent unauthorized discharges of solids and oil into waters of the

State.

Self Report? NO

Classification: Moderate 30 TAC Chapter 305, SubChapter F 305.125(1)

Citation:

PERMIT 00449-000 Page 2, No. 1 & Page 2d, no. 1 Rqmt Prov:

Failure to maintain compliance with the self-monitored, permitted effluent limits for Description:

Total Suspended Solids, Oil & Grease, and Total Zinc.

Date: 02/21/2006

Self Report?

Citation:

(455248)

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter A 382.085(b)

Rqmt Prov: PA No. 39142

Exceeded permit limits during an avoidable emissons event Description:

(498220)Date: 04/30/2006

Classification: Moderate Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1) Citation:

TWC Chapter 26 26.121(a)

Failure to meet the limit for one or more permit parameter Description:

Date: 06/30/2006 (481516)

Classification: Moderate Self Report? NO

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Rgmt Prov:

PA 39142, SC No. 1

Description:

Failure to prevent an unplanned compressor shutdown resulting in unauthorized

emissions from flaring.

Date: 06/30/2006

(483867)

Self Report?

30 TAC Chapter 117, SubChapter B 117,206(e)(2)

Description:

RE exceeded the NH3 emission limit of 10 ppm set forth in 30 TAC 117.206(e)(2).

Date: 09/29/2006

(509876)

Self Report?

30 TAC Chapter 116, SubChapter G 116.715(a)

Citation:

Citation:

5C THC Chapter 382, SubChapter D 382.085(b) PA 39142, SC No. 1

Ramt Prov: Description:

Citation:

Exceeded permit limits during an avoidable emissions event.

Date: 01/31/2007

(544545)

Self Report?

30 TAC Chapter 305, SubChapter F 305.125(1)

Description:

Failure to meet the limit for one or more permit parameter (575353)

Date: 03/31/2007

TWC Chapter 26 26.121(a)

Self Report? Citation:

30 TAC Chapter 305, SubChapter F 305.125(1) TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Date: 04/04/2007 (539574)

Self Report?

Classification:

Classification:

Classification:

Classification:

Classification:

Moderate

Moderate

Moderate

Moderate

Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b)

Ramt Prov: Description: PA 39142, SC No. 1

Date: 04/10/2007

Exceeded permit limits during an avoidable emissions event. (543996)

Classification:

Moderate

Self Report? Citation:

30 TAC Chapter 116, SubChapter G 116.715(a)

5C THC Chapter 382, SubChapter D 382.085(b) PA 39142, SC No. 1

Ramt Prov: Description:

Exceeded permit limits during an avoidable emissions event.

Date: 06/04/2007 (561098)

Self Report?

Classification:

Moderate

Citation:

30 TAC Chapter 116, SubChapter G 116.715(a) 5C THC Chapter 382, SubChapter D 382.085(b)

Rqmt Prov:

PERMIT 39142, SC No. 1 Failure to exercise good maintenance practices.

Description:

Date: 06/30/2007

Self Report? Citation:

(575356)

30 TAC Chapter 305, SubChapter F 305.125(1)

TWC Chapter 26 26.121(a)

Description:

Failure to meet the limit for one or more permit parameter

Date: 07/31/2007 (607555)

Classification:

Classification:

Moderate

Moderate

Self Report? Citation:

2D TWC Chapter 26, SubChapter A 26.121(a) 30 TAC Chapter 305, SubChapter F 305.125(1)

Description:

Failure to meet the limit for one or more permit parameter

Environmental audits.

G. Type of environmental management systems (EMSs).

Н. Voluntary on-site compliance assessment dates.

Participation in a voluntary pollution reduction program.

N/A

Early compliance.

N/A

Sites Outside of Texas

N/A

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY



IN THE MATTER OF AN	§	BEFORE THE
ENFORCEMENT ACTION	§	
CONCERNING	Š	TEXAS COMMISSION ON
VALERO REFINING-TEXAS, L.P.	Š	
RN100238385	§	ENVIRONMENTAL QUALITY
	§ §	ENVIRONMENTAL QUALIT

AGREED ORDER DOCKET NO. 2007-2039-AIR-E

I. JURISDICTION AND STIPULATIONS

At its ______ agenda, the Texas Commission on Environmental Quality ("the Commission" or "TCEQ") considered this agreement of the parties, resolving an enforcement action regarding Valero Refining-Texas, L.P. ("the Respondent") under the authority of Tex. Health & Safety Code ch. 382 and Tex. Water Code ch. 7. The Executive Director of the TCEQ, through the Enforcement Division, and the Respondent appear before the Commission and together stipulate that:

- 1. The Respondent owns and operates an oil and gas refining operation at 1301 Loop 197 South in Texas City, Galveston County, Texas (the "Plant").
- 2. The Plant consists of one or more sources as defined in Tex. Health & Safety Code § 382.003(12).
- 3. The Commission and the Respondent agree that the Commission has jurisdiction to enter this Agreed Order, and that the Respondent is subject to the Commission's jurisdiction.
- 4. The Respondent received notice of the violations alleged in Section II ("Allegations") on or about December 10, 2007.
- 5. The occurrence of any violation is in dispute and the entry of this Agreed Order shall not constitute an admission by the Respondent of any violation alleged in Section II ("Allegations"), nor of any statute or rule.
- 6. An administrative penalty in the amount of Ten Thousand Dollars (\$10,000) is assessed by the Commission in settlement of the violations alleged in Section II ("Allegations"). The Respondent has paid Four Thousand Dollars (\$4,000) of the administrative penalty and Two Thousand Dollars (\$2,000) is deferred contingent upon the Respondent's timely and satisfactory compliance with all the terms of this Agreed Order. The deferred amount will be waived upon full

compliance with the terms of this Agreed Order. If the Respondent fails to timely and satisfactorily comply with all requirements of this Agreed Order, the Executive Director may require the Respondent to pay all or part of the deferred penalty. Four Thousand Dollars (\$4,000) shall be conditionally offset by the Respondent's completion of a Supplemental Environmental Project ("SEP").

- 7. Any notice and procedures, which might otherwise be authorized or required in this action, are waived in the interest of a more timely resolution of the matter.
- 8. The Executive Director of the TCEQ and the Respondent have agreed on a settlement of the matters alleged in this enforcement action, subject to the approval of the Commission.
- 9. The Executive Director may, without further notice or hearing, refer this matter to the Office of the Attorney General of the State of Texas ("OAG") for further enforcement proceedings if the Executive Director determines that the Respondent has not complied with one or more of the terms or conditions in this Agreed Order.
- 10. This Agreed Order shall terminate five years from its effective date or upon compliance with all the terms and conditions set forth in this Agreed Order, whichever is later.
- 11. The provisions of this Agreed Order are deemed severable and, if a court of competent jurisdiction or other appropriate authority deems any provision of this Agreed Order unenforceable, the remaining provisions shall be valid and enforceable.

II. ALLEGATIONS

As owner and operator of the Plant, the Respondent is alleged to have failed to maintain an emission rate below the maximum allowable emission limits from Boiler 27 [emission point number ("EPN EB-27")], Boiler 28 ("EPN EB-28"), No. 1 Flare Stack ("EPN EFL-01"), No. 2 Flare Stack ("EPN EFL-02"), No. 3 Flare Stack ("EPN EFL-03"), and No. 4 Flare Stack ("EPN EFL-04"), in violation of 30 Tex. Admin. Code § 116.715(a), Permit No. 39142, Special Condition No. 1, and Tex. Health & Safety Code § 382.085(b), as documented during an investigation conducted on November 28, 2007. Specifically, 1,730 pounds ("lbs") of volatile organic compounds, 890.7 lbs of sulfur dioxide, 86.9 lbs of nitrogen oxides, 18.5 lbs of carbon dioxide, and 10 lbs of hydrogen sulfide were emitted on September 27, 2007 in a 2 hour, 1 minute period.

III. DENIALS

The Respondent generally denies each allegation in Section II ("Allegations").

IV. ORDERING PROVISIONS

1. It is, therefore, ordered by the TCEQ that the Respondent pay an administrative penalty as set forth in Section I, Paragraph 6 above. The payment of this administrative penalty and the Respondent's compliance with all the terms and conditions set forth in this Agreed Order resolve only the allegations in Section II. The Commission shall not be constrained in any manner from requiring corrective action or penalties for violations, which are not raised here. Administrative penalty payments shall be made payable to "TCEQ" and shall be sent with the notation "Re: Valero Refining-Texas, L.P., Docket No. 2007-2039-AIR-E" to:

Financial Administration Division, Revenues Section Attention: Cashier's Office, MC 214 Texas Commission on Environmental Quality P.O. Box 13088 Austin, Texas 78711-3088

- 2. The Respondent shall implement and complete a SEP in accordance with TEX. WATER CODE § 7.067. As set forth in Section I, Paragraph 6 above, Four Thousand Dollars (\$4,000) of the assessed administrative penalty shall be offset with the condition that the Respondent implement the SEP defined in Attachment A, incorporated herein by reference. The Respondent's obligation to pay the conditionally offset portion of the administrative penalty assessed shall be discharged upon final completion of all provisions of the SEP agreement.
- 3. It is further ordered that the Respondent shall undertake the following technical requirements:
 - a. Within 30 days after the effective date of this Agreed Order, develop and implement measures to improve design, operations, and/or maintenance practices to prevent the reoccurrence of events similar to the emission events that occurred on September 27, 2007; and
 - b. Within 45 days after the effective date of this Agreed Order, submit written certification as described below, and include detailed supporting documentation including photographs, receipts, and/or other records to demonstrate compliance with Ordering Provision No. 3.a. The certification shall be notarized by a State of Texas Notary Public and include the following certification language:

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

The certification shall be submitted to:

(1/2) (2/4) = (1/2) (2/4) (2/4) + (1/2) (2/4) (2/4) = (1/2) (2/4) (2/4) (2/4) = (1/2) (2/4) (2/4) (2/4) = (1/2) (2/4) (2/4) (2/4) = (1/2) (2/4) (2

Valero Refining-Texas, L.P. DOCKET NO. 2007- 2039-AIR-E Page 4

Order Compliance Team
Enforcement Division, MC 149A
Texas Commission on Environmental Quality
P.O. Box 13087
Austin, Texas 78711-3087

with a copy to:

Air Section Manager Houston Regional Office Texas Commission on Environmental Quality 5425 Polk Street, Suite H Houston, Texas 77023-1452

- 4. The provisions of this Agreed Order shall apply to and be binding upon the Respondent. The Respondent is ordered to give notice of the Agreed Order to personnel who maintain day-to-day control over the Plant operations referenced in this Agreed Order.
- 5. If the Respondent fails to comply with any of the Ordering Provisions in this Agreed Order within the prescribed schedules, and that failure is caused solely by an act of God, war, strike, riot, or other catastrophe, the Respondent's failure to comply is not a violation of this Agreed Order. The Respondent shall have the burden of establishing to the Executive Director's satisfaction that such an event has occurred. The Respondent shall notify the Executive Director within seven days after the Respondent becomes aware of a delaying event and shall take all reasonable measures to mitigate and minimize any delay.
- 6. The Executive Director may grant an extension of any deadline in this Agreed Order or in any plan, report, or other document submitted pursuant to this Agreed Order, upon a written and substantiated showing of good cause. All requests for extensions by the Respondent shall be made in writing to the Executive Director. Extensions are not effective until the Respondent receives written approval from the Executive Director. The determination of what constitutes good cause rests solely with the Executive Director.
- 7. This Agreed Order, issued by the Commission, shall not be admissible against the Respondent in a civil proceeding, unless the proceeding is brought by the OAG to: (1) enforce the terms of this Agreed Order; or (2) pursue violations of a statute within the Commission's jurisdiction, or of a rule adopted or an order or permit issued by the Commission under such a statute.
- 8. This agreement may be executed in multiple counterparts, which together shall constitute a single original instrument. Any executed signature page to this Agreement may be transmitted by facsimile transmission to the other parties, which shall constitute an original signature for all purposes.
- 9. Under 30 Tex. ADMIN. Code § 70.10(b), the effective date is the date of hand-delivery of the Order to the Respondent, or three days after the date on which the Commission mails notice of the Order to the Respondent, whichever is earlier. The Chief Clerk shall provide a copy of this Agreed Order to each of the parties.

en kan di kanada di

en de la composition La composition de la La composition de la

Valero Refining-Texas, L.P. DOCKET NO. 2007-2039-AIR-E Page 5

For the Commission

Valero Refining-Texas, L.P.

Section at the address in Section IV, Paragraph 1 of this Agreed Order.

SIGNATURE PAGE

I, the undersigned, have read and understand the attached Agreed Order. I am authorized to agree to the attached Agreed Order on behalf of the entity indicated below my signature, and I do agree to the terms

TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

and conditions specified therein. I further acknowledge that penalty amount, is materially relying on such representation.	t the TCEQ, in accepting payment for the
 I also understand that failure to comply with the Ordering Protimely pay the penalty amount, may result in: A negative impact on compliance history; Greater scrutiny of any permit applications submitted; Referral of this case to the Attorney General's Office penalties, and/or attorney fees, or to a collection agence increased penalties in any future enforcement actions; Automatic referral to the Attorney General's Office of TCEQ seeking other relief as authorized by law. In addition, any falsification of any compliance documents may 	e for contempt, injunctive relief, additional y; any future enforcement actions; and
Signature Adrian Avaiza Name (Printed or typed) Authorized Representative of	Date / 2008 Manager, Enumerated Affairs. Title

Instructions: Send the original, signed Agreed Order with penalty payment to the Financial Administration Division, Revenues

•

Attachment A Docket Number: 2007-2039-AIR-E

SUPPLEMENTAL ENVIRONMENTAL PROJECT

Respondent: Valero Refining-Texas, L.P.

Payable Penalty Amount: Eight Thousand Dollars (\$8,000)

SEP Amount: Four Thousand Dollars (\$4,000)

Type of SEP: Pre-approved

Third-Party Recipient: Houston-Galveston AERCO's Clean Cities/Clean Vehicles

Program

Location of SEP: Galveston County

The Texas Commission on Environmental Quality ("TCEQ") agrees to offset a portion of the administrative Penalty Amount assessed in this Agreed Order for the Respondent to contribute to a Supplemental Environmental Project ("SEP"). The offset is equal to the SEP Amount set forth above and is conditioned upon completion of the project in accordance with the terms of this Attachment A.

1. Project Description

A. Project

The Respondent will contribute to Houston-Galveston AERCO's Clean Cities/Clean Vehicles Program in Galveston County. The contribution will be used in accordance with the *Supplemental Environmental Project Agreement between the Houston-Galveston AERCO and the Texas Commission on Environmental Quality*. SEP monies will be used to aid local school districts and area transit agencies in reaching local match requirements mandated by the Federal Highway Administration's ("FHWA") Congestion Mitigation/Air Quality funding program. SEP monies will be disbursed to school districts and transit agencies in need of funding assistance in the Houston-Galveston non-attainment area. Those SEP monies will be used exclusively by the school districts and transit agencies as supplements to meet the local match requirements of the EPA. SEP monies will be used to pay for the cost of replacing older diesel buses with alternative fueled or clean diesel buses. The old buses will be permanently retired and only sold for scrap. The schools and transit agencies will also use the SEP monies to retrofit more buses to reduce emissions. Houston-Galveston AERCO will send the TCEQ verification in the form of paid invoices and other documentation to show that the retrofits were completed. Retrofit technologies include particulate matter traps, diesel particulate matter filters, NOx reduction catalyst technology in combination with diesel particulate filters, and other emission control technologies that are developed and approved by EPA or the California Air Resources Board.

The Respondent certifies that there is no prior commitment to do this project and that it is being performed solely in an effort to settle this enforcement action.

B. Environmental Benefit

This SEP will provide a discernible environmental benefit by reducing particulate emissions on buses by more than 90% below today's level and reducing hydrocarbons below measurement capability.

C. <u>Minimum Expenditure</u>

The Respondent shall contribute at least the SEP Amount to the Third-Party Recipient and comply with all other provisions of this SEP.

2. Performance Schedule

Within 30 days after the effective date of this Agreed Order, the Respondent must contribute the SEP Amount to the Third-Party Recipient. The Respondent shall mail the contribution, with a copy of the Agreed Order, to:

Houston-Galveston Area Council Houston-Galveston AERCO P.O. Box 22777 Houston, Texas 77227-2777

3. Records and Reporting

Concurrent with the payment of the SEP Amount, the Respondent shall provide the TCEQ SEP Coordinator with a copy of the check and transmittal letter indicating full payment of the SEP Amount to the Third-Party Recipient. The Respondent shall mail a copy of the check and transmittal letter to:

Enforcement Division Attention: SEP Coordinator, MC 219 Texas Commission on Environmental Quality P.O. Box 13087 Austin, Texas 78711-3087

4. Failure to Fully Perform

If the Respondent does not perform its obligations under this SEP in any way, including full payment of the SEP Amount and submittal of the required reporting described in Section 3 above, the Executive Director may require immediate payment of all or part of the SEP Amount.

The check for any amount due shall be made out to "Texas Commission on Environmental Quality" and mailed to:

Texas Commission on Environmental Quality Financial Administration Division, Revenues Attention: Cashier, MC 214 P.O. Box 13088 Austin, Texas 78711-3088

en grande de la companya de la comp La companya de la co Valero Refining-Texas, L.P. Agreed Order – Attachment A

The Respondent shall also mail a copy of the check to the TCEQ SEP Coordinator at the address in Section 3 above.

5. Publicity

Any public statements concerning this SEP made by or on behalf of the Respondent must include a clear statement that the project was performed as part of the settlement of an enforcement action brought by the TCEQ. Such statements include advertising, public relations, and press releases.

6. Clean Texas Program

The Respondent shall not include this SEP in any application made to TCEQ under the "Clean Texas" (or any successor) program(s). Similarly, the Respondent may not seek recognition for this contribution in any other state or federal regulatory program.

7. Other SEPs by TCEQ or Other Agencies

The SEP identified in this Agreed Order has not been, and shall not be, included as an SEP for the Respondent under any other Agreed Order negotiated with the TCEQ or any other agency of the state or federal government.

e de la companya de l